

BELZONA RESTORES TUBE SHEET PROTECTION

CUSTOMER

Power station, Cairo, Egypt

APPLICATION DATE

September 2003

APPLICATION SITUATION

Condenser Tube Sheet

PROBLEM

Original coating on tube sheet had failed. Replacement required to prevent future corrosion.

PRODUCTS

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Carbon Steel

APPLICATION METHOD


The application was carried out in accordance with Belzona System Leaflet HEX-3.

BELZONA FACTS

The Belzona repair was carried out quickly, minimizing outage time. Belzona® 1321 has a long track record of providing corrosion protection on such equipment.

PICTURES

1. Damaged original coating
2. After surface preparation
3. First coat of Belzona® 1321 applied
4. Second coat of Belzona 1321 applied



For more examples of *Belzona Know-How In Action*, please visit <http://khia.belzona.com>



Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

UK • USA • Canada • China
www.belzona.com

